B

	Aliestic- No	Applicant(s)
Notice of Allowability	Application No.	Applicant(s)
	10/532,695	STEINRUECKEN ET AL.
	Examiner	Art Unit
	Walter Benson	2858
The MAILING DATE of this communication appears on the cover sheet with the correspondence address All claims being allowable, PROSECUTION ON THE MERITS IS (OR REMAINS) CLOSED in this application. If not included herewith (or previously mailed), a Notice of Allowance (PTOL-85) or other appropriate communication will be mailed in due course. THIS NOTICE OF ALLOWABILITY IS NOT A GRANT OF PATENT RIGHTS. This application is subject to withdrawal from issue at the initiative of the Office or upon petition by the applicant. See 37 CFR 1.313 and MPEP 1308.		
1. This communication is responsive to <u>Amendment filed 3/28/06 and telephonic interview</u> .		
2. The allowed claim(s) is/are <u>1-12</u> .		
 3. Acknowledgment is made of a daim for foreign priority un a) All b) Some* c) None of the: 1. Certified copies of the priority documents have 		
2. Certified copies of the priority documents have been received in Application No		
3. Copies of the certified copies of the priority documents have been received in this national stage application from the		
International Bureau (PCT Rule 17.2(a)).		
* Certified copies not received:		
Applicant has THREE MONTHS FROM THE "MAILING DATE" of this communication to file a reply complying with the requirements noted below. Failure to timely comply will result in ABANDONMENT of this application. THIS THREE-MONTH PERIOD IS NOT EXTENDABLE.		
4. A SUBSTITUTE OATH OR DECLARATION must be submitted. Note the attached EXAMINER'S AMENDMENT or NOTICE OF INFORMAL PATENT APPLICATION (PTO-152) which gives reason(s) why the oath or declaration is deficient.		
5. CORRECTED DRAWINGS (as "replacement sheets") must be submitted.		
(a) ☑ including changes required by the Notice of Draftsperson's Patent Drawing Review (PTO-948) attached		
1) 🗵 hereto or 2) 🔲 to Paper No./Mail Date		
(b) ☐ including changes required by the attached Examiner's Amendment / Comment or in the Office action of Paper No./Mail Date		
Identifying indicia such as the application number (see 37 CFR 1.84(c)) should be written on the drawings in the front (not the back) of each sheet. Replacement sheet(s) should be labeled as such in the header according to 37 CFR 1.121(d).		
6. DEPOSIT OF and/or INFORMATION about the deposit of BIOLOGICAL MATERIAL must be submitted. Note the attached Examiner's comment regarding REQUIREMENT FOR THE DEPOSIT OF BIOLOGICAL MATERIAL.		
Attachment(s)		·
1. Notice of References Cited (PTO-892)		atent Application (PTO-152)
2. Notice of Draftperson's Patent Drawing Review (PTO-948)	6. ⊠ Interview Summary (Paper No./Mail Date	
3. A Information Disclosure Statements (PTO-1449 or PTO/SB/0	8), 7. ⊠ Examiner's Amendm	
Paper No./Mail Date <u>4/28/05</u> 4. Examiner's Comment Regarding Requirement for Deposit	8. Examiner's Stateme	ent of Reasons for Allowance
of Biological Material	9.	
		•
		ļ
		;

Application/Control Number: 10/532,695 Page 2

Art Unit: 2858

EXAMINER'S AMENDMENT

1. An examiner's amendment to the record appears below. Should the changes and/or-

additions be unacceptable to applicant, an amendment may be filed as provided by 37 CFR

1.312. To ensure consideration of such an amendment, it MUST be submitted no later than the

payment of the issue fee.

2. Authorization for this examiner's amendment was given in a telephone interview with

Ilya. Zborovsky, Reg. No. 28563 on 4/10/06.

3. In Amendment to the claims filed 3/28/06:

I. In claim 1:

1. (currently amended) A method for diagnosis of a sensor in a motor vehicle having an

internal combustion engine, comprising the following steps:

during operation of the motor vehicle, monitoring an output signal of the sensor for

whether a maximum value of the output signal undershoots a first threshold value and/or a

minimum value of the output signal overshoots a second threshold value;

forwarding a signal to a controller that signals to the controller that the sensor, upon

restarting of the motor vehicle, might be furnishing incorrect data if the maximum value of the

output signal undershoots the first threshold value and/or the minimum value of the output signal

overshoots the second threshold value; and

Art Unit: 2858

wherein the undershooting or exceeding of the threshold value is used for diagnosis of the sensor.

Allowable Subject Matter

4. Claims 1-12 are allowed over the prior art of record.

The prior art of record fails to teach in combination as claimed a method for diagnosis of a sensor in a motor vehicle having an internal combustion engine, including during operation of the motor vehicle, monitoring an output signal of the sensor for a maximum/undershoot value compared to first and second threshold values. Forwarding a signal to a controller that signals to the controller that the sensor, upon restarting of the motor vehicle, might be furnishing incorrect data if the maximum value of the output signal undershoots the first threshold value and/or the minimum value of the output signal overshoots the second threshold value. The undershooting or exceeding of the threshold value is used for diagnosis of the sensor.

Contact Information

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Walter Benson whose telephone number is (571) 272-2227. The examiner can normally be reached on Mon to Fri 6:30 AM to 4:00 PM.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Diane Lee can be reached on (571) 272-2399. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Application/Control Number: 10/532,695

Art Unit: 2858

Information regarding the status of an application may be obtained from the Patent

Page 4

Application Information Retrieval (PAIR) system. Status information for published applications

may be obtained from either Private PAIR or Public PAIR. Status information for unpublished

applications is available through Private PAIR only. For more information about the PAIR

system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR

system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

Primary Examiner

April 10, 2006